

STATE OF FLORIDA  
DEPARTMENT OF HEALTH  
COUNTY HEALTH DEPARTMENT  
PUBLIC SCHOOL  
INSPECTION REPORT



1 of 2

**Facility Information**

**RESULT: Satisfactory**

Permit Number: 13-51-1367913  
Name of Facility: North County K-8 Ctr.  
Address: 3250 NW 207 Street  
City, Zip: Miami 33056  
  
Type: Public Schools  
Owner: Miami-Dade County School Board  
Person In Charge: Aisha Marrero Phone: (305) 624-9648  
PIC Email: amarrero@dadeschools.net

**Correct By: Next Inspection**  
**Re-Inspection Date: None**

**Inspection Information**

Purpose: Routine  
Inspection Date: 8/11/2020

Begin Time: 10:00 AM  
End Time: 11:00 AM

**Additional Information**

FEMALES ..... CENSUS ..... 368  
MALES .....

*This form serves as a "Notice of Non-Compliance" pursuant to section 120.695, Florida Statutes. Items marked below violate one or more of the requirements of Rule 6A-2.0010, of the Florida Administrative Code, Chapter 5, section 5 of the State Requirements for Educational Facilities 2014 (SREF); and sections 453 and 468 of the Florida Building Code 6th Edition (2017). Violations must be corrected within the time period indicated above. Continued operation of this facility without making these corrections is a violation. Failure to correct violations in the time frame specified may result in enforcement action being initiated by the Department of Health.*

**Violation Markings**

SCHOOL SANITATION	<b>IN</b> 11. Group Toilet Rooms	<b>IN</b> 21. Pest Control
<b>IN</b> 1. School Site	<b>IN</b> 12. Toilet Facilities	SAFETY
<b>IN</b> 2. Playground, Equip & Athletic Fields*	<b>OUT</b> 13. Handwashing Facilities	<b>IN</b> 22. First Aid Kit
<b>IN</b> 3. Athletic & Playground Equipment	<b>IN</b> 14. Soap Dispensers	DIAPER CHANGING STATION
BUILDING CONST/MAINT.	<b>IN</b> 15. Shower Facilities	<b>NA</b> 23. Sanitizers
<b>IN</b> 4. Construction	<b>IN</b> 16. Showers Water Temperatures	<b>NA</b> 24. Changing Station & Mats
<b>OUT</b> 5. Maintenance & Repair	WATER SUPPLY	<b>NA</b> 25. Hand Sink
<b>IN</b> 6. Lighting Standards	<b>IN</b> 17. Approved Source	<b>NA</b> 26. Garbage Can
<b>IN</b> 7. Heating, Ventilation, A/C Standards	<b>IN</b> 18. Drinking Fountains	ANIMAL HEALTH & SAFETY
<b>IN</b> 8. Natural Ventilation	LIQUID WASTE & WASTE WATER	<b>NA</b> 27. Animal Maintenance/Aggressive
<b>IN</b> 9. Mechanical Ventilation	<b>IN</b> 19. Sewage Disposal	DORM/RESIDENTIAL FACILITIES
SANITARY FACILITIES	<b>IN</b> 20. Solid Waste	<b>NA</b> 28. Maintenance/Complaint
<b>IN</b> 10. Provided/Accessible/Separation	PEST CONTROL	<b>NA</b> 29. Other

Marking Key: **IN** = the act or item was observed to meet standards; **OUT** = the act or item was observed not to meet standards; **NO** = the act or item was not observed to be occurring at the time of inspection; **NA** = the act or item is not performed by the facility or not part of the operation

Violation Key: \* = 2. Playground, Equipment & Athletic Fields

Inspector Signature:

*J Scott*

Client Signature:

*Email to client*

STATE OF FLORIDA  
DEPARTMENT OF HEALTH  
COUNTY HEALTH DEPARTMENT  
PUBLIC SCHOOL  
INSPECTION REPORT



2 of 2

### General Comments

Extensive renovation in progress in Buildings 1, 3, 6 & in the Cafeteria. Scope of work includes the replacement of AC systems, rewiring of Fire Alarm system, replacement of cabinetry, replacement of floor tiles, remodeling of restrooms and replacement of windows.

Only Building 4 and the Annex were assessed.

Email Address(es): amarrero@dadeschools.net;  
IPalacio@dadeschools.net;  
JWare@dadeschools.net;  
jaybolton@dadeschools.net;

### Violations Comments

Violation #5. Maintenance & Repair  
Water stained ceiling tiles in Rooms 101 & 107. Replace ceiling tiles.

CODE REFERENCE: 5. Maintenance and Repair. 5(1)(e)8.h SREF. Light fixtures and window surfaces, both inside and outside, shall be kept clean, serviceable, and in good repair at all times. 5(1)(e)8.i. Custodial areas shall be kept clean, safe, and orderly at all times. Custodial equipment shall be in good repair at all times. 5(1)(e)8.j SREF. Building components & finishes shall be kept clean & in good repair.

Violation #13. Handwashing Facilities  
Missing push bar at two of four sprouts at each hand wash sink within both Male Restroom 110 and Female Restroom 109 (No water at two of four sprouts in each restroom). Replace push bars.

CODE REFERENCE: 13. Handwashing Facilities. 5(13)(h)1 SREF. Hot and cold water shall be provided in toilet rooms at the lavatory. Hot water temperature shall not exceed 110°F. 468.3.5.7.1 FBC. Handwashing facilities shall be located within or adjoining each toilet room.

Inspection Conducted By: Jeffericia Scott (913251)  
Inspector Contact Number: Work: (305) 623-3500 ex.  
Print Client Name:  
Date: 8/11/2020

Inspector Signature:

*JScott*

Client Signature:

*Email to client*